MP 0.63 Bay City Creek (sase006p)



Photo looking northeast at existing slope instability area.



Photo looking east at existing slope instability area.



Photo looking south at pipeline crossing area.

MP 2.24 Little Beartrap Creek (sasa047i)



Photo looking east (downstream)



Photo looking south (across)



Photo looking west (upstream)

MP 2.91 Beartrap Creek (sasb007i)



Photo looking northwest (downstream)



Photo looking southwest (upstream)

MP 5.94 UNT Deer Creek (sasc039i)



Photo looking east (downstream)



Photo looking south (across)



Photo looking west (upstream)

MP 12.43 UNT Marengo River (sase1015i)



Photo looking northwest (downstream)



Photo looking southwest (upstream)

MP 14.73 UNT Brunsweiler River (sasc1006p)



Photo looking north (downstream)



Photo looking northwest (downstream)

MP 28.67 UNT Gehrman Creek (sasw011)



Photo looking north (downstream)



Photo looking south (upstream)