

## Wisconsin Line 5 Corridor Wetlands and Waterbodies Photos



Photo of a typical creek crossing on Line 5 in Wisconsin. Photo taken at [REDACTED] in June, 2022 in Bayfield County, Wisconsin. Photo represents typical vegetation and soils/substrate found along smaller creeks in Northern Wisconsin.



Photo of a typical ROW in large wetland complex in Iron County, Wisconsin. Photo taken at [REDACTED] in October, 2022. Photo represents typical hydrology and vegetation seen on pipeline corridors in forested wetlands in northern Wisconsin.





Line 5 crossing of an intermittent stream in Douglas County, Wisconsin. Photo was taken June 2012 at [REDACTED]. Photo represents a typical intermittent stream crossed by a pipeline corridor in northern Wisconsin.



Line 5 corridor in a typical wetland complex in northern Wisconsin. Photo shows representative vegetation commonly found in pipeline corridors in Bayfield County, Wisconsin. Photo taken October 2017 at [REDACTED].





Line 5 corridor in a typical wetland. Photo shows common vegetation and conditions observed in northern Wisconsin wetlands within the Line 5 corridor. Photo taken in Iron County, Wisconsin in November 2022. Photo taken at [REDACTED] .



Typical wetland found along Line 5 corridor in Northern Wisconsin. Vegetation representative of species commonly observed. Photo taken October, 2018 at [REDACTED] in Ashland County, Wisconsin.





Typical wetland found in Line 5 corridor. Species and vegetative cover is representative of wetlands found in pipeline corridors in northern Wisconsin. Photo taken October 2017 at [REDACTED] in Bayfield County, Wisconsin.



Wetland and intermittent waterway along line 5 corridor in Ashland County, Wisconsin. Species of vegetation are representative of those found along the line 5 corridor in northern Wisconsin. Photo taken in November 2017 at [REDACTED].





NWI classified PEM wetland along Line 5 corridor in Douglas County, Wisconsin. Photo taken in November 2014 at [REDACTED].



NWI classified PEM wetland along Line 5 Corridor in Douglas County, Wisconsin. Photo taken in October 2017 at [REDACTED].





Photo of a typical creek crossing on Line 5 corridor in Douglas County, Wisconsin. Photo taken at [REDACTED] in August 2017. Photo represents typical vegetation and creek conditions encountered on Line 5 corridor.



Photo of a typical creek crossing on the Line 5 corridor in Bayfield County, Wisconsin. Photo taken at [REDACTED] in June 2015. Photo represents a typical creek crossing and vegetation encountered on the Line 5 corridor in northern Wisconsin.